


FIGURE 4

Highway 9: Waterman Gap Hairpin Ccurve

This segment of Highway 9, located at a hairpin turn south of the intersection with SR 236 and north of Saratoga Toll Road, is classified as Undeveloped Mountainous. The road is narrow with horizontal and vertical curves that present challenges related to sight distance, especially navigating tight or compounding curves. Anecdotal reports of speeding and racing on this portion of Highway 9 were shared in the community feedback. Although observed speed data shows average speeds of approximately 30 MPH, the corridor has a history of lane departure and DUI-related crashes.



KEY ENHANCEMENTS

- Install centerline rumble strips
- Manage vegetation to maintain visibility
- Install speed feedback signs to encourage slower travel speeds
- Enhance speed enforcement opportunities

PLACE TYPE

Undeveloped Mountainous


SEGMENT LENGTH

500 Feet

PROFILES ADDRESSED

Lane Departures, DUIs on Undeveloped Mountainous Roads

CRASH OUTCOMES



CRASH BY MODE

